

FIG. 1





FIG. 2



BOP	FUSE	H30	H25	H18
0	0	1	0	0
0	1	0	1	0
1	0	0	0	1
1	1	0	0	1

H18="1" : Vcc=1.8V

H25="1" : Vcc=2.5V

H30="1" : Vcc=3.0V

FIG. 3





FIG. 4








**FIG. 7****FIG. 8****FIG. 9**

FIG. 10




FIG. 11




FIG. 12(A)





FIG. 12(B)





*FIG. 13**FIG. 14*







FIG. 17




FIG. 18




FIG. 19





FIG. 20





*FIG. 21*

FIG. 22




*FIG. 23*



FIG. 24




FIG. 25




FIG. 26




FIG. 27




FIG. 28







FIG. 29




*FIG. 30*

*FIG. 31*



*FIG. 32(A)*



*FIG. 32(B)*

